



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

Date: March 12, 2009

Reviewed:

<b>Mine Name:</b> Cane Springs	<b>Permit Number:</b> S/045/0073
<b>Operator Name:</b> Clifton Mining Co.	<b>Inspection Date:</b> 06-11-2008
<b>Inspector(s):</b> L Hepler	<b>Time:</b> 10:00 AM
<b>Other Participants:</b> none	<b>Mine Status:</b> PRO

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Amount:** Bond not posted **Permit fee** is up to date

**Purpose of Inspection:** Routine annual Inspection

**Inspection Summary:** Several declines and shafts are fenced but open. Two recent drill sites have been regraded and are shown in the attached photographs. Revegetation is limited. Topsoil is limited.

Photos were taken to document site conditions.

**Conclusions and Recommendations:** Permit should either be changed to a small mine permit or closed out. OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature**

09-09-09

LAH:vs

cc: Keith Moeller

[Larry\\_Garahana@blm.gov](mailto:Larry_Garahana@blm.gov) [Stephen\\_Allen@blm.gov](mailto:Stephen_Allen@blm.gov)

O:\M045-Tooele\S0450073-CaneSprings\inspections\insp-06112008.doc

